


 **COPY**



Neville Levey  
Director of Engineering Services  
Shire of Broome  
Weld Street  
BROOME WA 6725

Clive Johnson  
Site 61 Roebuck Bay Caravan Park  
BROOME WA 6725  
0438 929978

10<sup>th</sup> November 2010

FILE:	RES31340 208-2/83	
ACTION OFFICER:	DES <i>Report Required</i>	
ACTION: (sign & date)	<i>DL</i> NOTED	RESPONDED
RECORD NO:	1101111-56424	
FURTHER REFERRAL	Already received by	
ACTION OFFICER	E-mail / Fax	
ACTION REQUIRED	NOTE or RESPOND	


Dear Neville

Re: Erosion of the Beach between Mangrove Point and Catalina Units.

As you are aware we have thousands of locals and tourists visiting this area to view Stairway to the Moon utilising Mangrove Point to view this event. Close to edge of the Pioneer Cemetery there is a 6 metre drop into the Bay. The bank in question has an undercut and the top the bank has eroded to within 300 millimetres of the 'safety fence' due to the years of high tides taking their toll making this area extremely dangerous.

The stretch of Beach Mangrove Point to the Catalina Units is also suffering from erosion. For example a length of railway line inspected 3 years ago sitting on the top of the bank approx 1 metre from the edge and is now at the edge threatening to fall approx 6 metres into the Bay. This is a popular area for Aboriginal Communities to gather therefore I believe this situation is critical and requires your urgent attention.

Yours faithfully



Clive Johnson  
Photographs attached.